


Battery Replacement



Battery Indicator




P5R Signature




Charging

0°C - 40°C





Hand Strap




Charging Station


0°C - 40°C





Remove Water from Charging Port







Ledlenser GmbH & Co. KG,
Kronenstr. 5-7, 42699 Solingen, Germany
Phone +49 212/5948-0 info@ledlenser.com


www.ledlenser.com

Operation





Advanced Focus System



Transportation Lock

